APPENDIX D
SITE PHOTOGRAPHS



Photo 1 Looking northeast across surface of Oxide Tailings Area ("mounds" in foreground). (1/23/2002)



Photo 2 Looking southward along west face of Oxide Tailings Area. (7/12/2002)



Photo 3
Looking southwest over Sulfide Tailings with agricultural fields in foreground. (1/23/2002)



Photo 4
Looking southward over VLT-covered surface of Sulfide Tailings Area – saltcedar and other shrub growth. (5/24/2002)



Photo 5 Looking southwest over Process Solution Recycling Ponds. (1/23/2002)



 $\begin{array}{c} Photo\ 6\\ Looking\ southwest\ over\ Unlined\ Evaporation\ Ponds\ to\ the\ east\ and\ north\\ of\ the\ Phase\ IV-VLT\ Heap\ Leach.\ (1/23/2002) \end{array}$



Photo 7
Looking west over lined Pumpback Evaporation Ponds, Lined
Evaporation Ponds and the Weed Heights Sewage Lagoons. (1/23/2002)



Photo 8
Looking west at north face of Oxide Tailings and abandoned crusher or bin support structure. (7/12/2002)